

## **TECHNICAL DATASHEET**

# Woven Heatseal Badges



# Woven Heatseal Badges



### **TECHNICAL DATASHEET**

www.ja-int.com

#### **APPLICATION**

Temperature (°C): 140-160°C Temperature (°F): 284-320°F Time: 15 seconds

Pressure: Medium 42.7 - 56.9 psi / 2.9 - 3.9 bar / 3.0 - 4.0 kg/cm2

#### **LAUNDERING**

Suitable for Domestic wash up to 60°C Suitable for Tumble drying Iron - Medium, On Reverse

#### HANDLING AND STORAGE

Store in a cool, dry environment Store away from direct sunlight

#### **COMPOSITION**

100% Polyester Thread Adhesive Backer - EVA Resin

#### **HEALTH & SAFETY**

This product is identified as Non-Hazardous to the end user No PPE is required during application\*\*

#### **ENVIRONMENTAL / RECYCLING**

Non-Recyclable

<sup>\*\*</sup>Any furnes created by this transfer during application are harmless. However, modern garment materials can be coated and finished in many different ways; some of which may alter their application and health & safety requirements. We recommend thorough checking and testing of any garment material to determine the correct requirements before application.